



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1
IV	Reprint of Maritime Safety Information	2

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
<http://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm>

Hydrographic Division
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : 1800 272 7777 / (65) 6272 7777
Fax : (65) 6226 1076
Email : hydrographic@mpa.gov.sg

II

TEMPORARY AND PRELIMINARY NOTICES

***(NM 106T/2021) : MAINTENANCE OF BANYAN BEACON**

Description	:	<ol style="list-style-type: none"> 1. Banyan Beacon at position Latitude 1°13'346"N Longitude 103°41'585'E has been removed for maintenance. 2. A temporary Isolated Danger Buoy with light characteristics Fl(2)10s has been installed at position Latitude 1°13'313"N Longitude 103°41'543'E. 3. Mariners are advised to navigate with caution.
Charts affected	:	Singaporean GSP1/SP1, 500, 501, Dual Badged BA4031, BA4032, BA4039, BA4040.
ENC affected	:	SG5C4032

*Source: Maritime and Port Authority of Singapore

***(NM 107P/2021) : REPLACEMENT OF BUOYS OFF TUAS FINGER ONE**

Description	:	<ol style="list-style-type: none"> 1. Two port-hand lateral buoys F1JV-02 at position Latitude 1°15'910"N Longitude 103°38'709'E and F1JV-03 at position Latitude 1°16'297"N Longitude 103°38'709'E have been removed. 2. A port-hand lateral buoy, TMS 3, with light characteristics Fl.R.5s, has been installed at position Latitude 1°16'194"N Longitude 103°38'709'E.
Charts affected	:	Singaporean GSP1/SP1, Dual Badged BA4030, BA4033, BA4038 and BA4040.
ENC affected	:	SG5C4030

*Source: Maritime and Port Authority of Singapore

IV

REPRINT OF MARITIME SAFETY INFORMATION

TT783 (AMENDED ON 221130UTC NOV 21)

BANYAN BEACON AT POSITION 01-13.346N 103-41.585E WAS REMOVED FOR MAINTENANCE. AN ISO
DANGER BUOY WITH LIGHT CHARACTER, FL(2)10S IS DEPLOYED AT POSITION 01-13.313N, 103-41.543E.

ISSUED BY SINGAPORE PORT OPERATIONS CONTROL CENTRE