



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
<http://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm>

Hydrographic Division
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : 1800 272 7777 / (65) 6272 7777
Email : hydrographic@mpa.gov.sg

II TEMPORARY AND PRELIMINARY NOTICES

***(NM 51T/2022) : MAINTENANCE OF BANYAN BEACON**

Description :	1.	Banyan Beacon at position Latitude 1°13'346"N Longitude 103°41'585'E with light characteristics Fl(2)10s is temporarily removed for maintenance.
	2.	A temporary Isolated Danger Buoy with light characteristics Fl(2)10s has been installed at position Latitude 1°13'315"N Longitude 103°41'546'E.
	3.	Mariners are advised to navigate with caution.
Charts affected :		Singaporean GSP1/SP1, 500, 501, Dual Badged BA4031, BA4032, BA4039, BA4040.
ENCs affected :		SG5C4032

*Source: Maritime and Port Authority of Singapore