



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Notices to Mariners and Chart Corrections	1
	Temporary and Preliminary Notices	2
IV	Reprint of Maritime Safety Information	3

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
<https://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm>

Hydrographic Division
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : (65) 6325 2027
Fax : (65) 6226 1076
Email : hydrographic@mpa.gov.sg
Website : www.mpa.gov.sg

II

NOTICES TO MARINERS AND CHART CORRECTIONS

202	8 Ed 15/09/2016 Last NM 82/2021 (Maritime and Port Authority of Singapore)		*NM 90/2021
Insert	limit of working area, pecked line, joining	1°19·63'N	104°24·08'E
		1°20·05'N	104°24·08'E
		1°20·28'N	104°24·51'E
		1°20·26'N	104°24·59'E
		1°20·18'N	104°24·70'E
		1°20·06'N	104°24·78'E
		1°19·88'N	104°24·84'E
		1°19·68'N	104°24·83'E
		1°19·63'N	104°24·80'E
	legend, <i>Works in progress (2021) (see Note)</i> , centred on:	1°19·68'N	104°25·07'E
	the accompanying block, centred on:	1°39·2'N	104°08·5'E

503	5 Ed 15/08/2014 Last NM 60/2021 (Maritime and Port Authority of Singapore)		*NM 90/2021
Insert	limit of working area, pecked line, joining	1°19·63'N	104°24·08'E
		1°20·05'N	104°24·08'E
		1°20·28'N	104°24·51'E
		1°20·26'N	104°24·59'E
		1°20·18'N	104°24·70'E
		1°20·06'N	104°24·78'E
		1°19·88'N	104°24·84'E
		1°19·68'N	104°24·83'E
		1°19·63'N	104°24·80'E
	legend, <i>Works in progress (2021) (see Note)</i> , centred on:	1°19·90'N	104°24·54'E
	the accompanying block, centred on:	1°02·3'N	104°33·6'E

II

TEMPORARY AND PRELIMINARY NOTICES

*(NM 91P/2021) : RECLAMATION WORKS IN THE VICINITY OF HORSBURGH LIGHTHOUSE

Description : Reclamation works will be conducted in the vicinity of Horsburgh Lighthouse

Reclamation Period : From 1st September 2021

1. The reclamation works conducted will be bounded by the following coordinates:

Coordinate of working area	Latitude (N)	Longitude (E)
1	1°19·63'N	104°24·08'E
2	1°20·05'N	104°24·08'E
3	1°20·28'N	104°24·51'E
4	1°20·26'N	104°24·59'E
5	1°20·18'N	104°24·70'E
6	1°20·06'N	104°24·78'E
7	1°19·88'N	104°24·84'E
8	1°19·68'N	104°24·83'E
9	1°19·63'N	104°24·80'E

2. Charts affected: Singaporean 202 and 503.
3. ENC's affected: MS3IK2EB and MS4NS2EB.
4. Mariners are advised to navigate with caution and give a wide berth to the working area.
5. Navigational warning broadcast will be promulgated by the relevant VTS Authorities via NAVTEX. Mariners are to maintain a listening watch.

Source: Maritime and Port Authority of Singapore

IV

REPRINT OF MARITIME SAFETY INFORMATION

TT765

CONDUCTING OF RECLAMATION WORKS BOUNDED BY THE FOLLOWING COORDINATES FROM 1 SEP 2021.

1	1°19·63'N	104°24·08'E
2	1°20·05'N	104°24·08'E
3	1°20·28'N	104°24·51'E
4	1°20·26'N	104°24·59'E
5	1°20·18'N	104°24·70'E
6	1°20·06'N	104°24·78'E
7	1°19·88'N	104°24·84'E
8	1°19·68'N	104°24·83'E
9	1°19·63'N	104°24·80'E


VESSELS PASSING IN THE VICINITY ARE ADVISED TO GIVE A WIDE BERTH AND NAVIGATE WITH CAUTION.

ISSUED BY SINGAPORE PORT OPERATIONS CONTROL CENTRE

To accompany Notice to Mariners

Image Size (mm) 76.1 by 45.7

WORKS IN PROGRESS (1°19.7'N 104°25.1'E)
Reclamation works are in progress in this working area. Mariners are advised to keep well clear and give a wide berth to the working area. Depths within the working area will be shallower as the reclamation progresses. Uncharted buoys may be present within the working areas.

Buk. Siti
97 


Block for Chart No 202

To accompany Notice to Mariners

Image Size (mm) 75.4 by 35.7

WORKS IN PROGRESS (1°19-9'N 104°24-5'E)

Reclamation works are in progress in this working area. Mariners are advised to keep well clear and give a wide berth to the working area. Depths within the working area will be shallower as the reclamation progresses. Uncharted buoys may be present within the working areas.



104° 35'

Block for Chart No 503