



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Notices to Mariners and Chart Corrections	1
	Temporary and Preliminary Notices	2

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
www.mpa.gov.sg/media-centre

MPA Telegram Channel: MPA has launched a Telegram channel for notices and circulars. To stay updated, please subscribe via the following link <https://go.gov.sg/mpa-telegram> or scan the QR code:



<https://go.gov.sg/mpa-telegram>

Contact information:

Hydrographic Division
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : 1800 272 7777 / (65) 6272 7777
Email : hydrographic@mpa.gov.sg

II
NOTICES TO MARINERS AND CHART CORRECTIONS

GSP1/SP1	8 Ed 17/01/24 Last NM 58/2024 (Maritime and Port Authority of Singapore)	*NM 66/2024
Insert	the accompanying block, centred on:	1°19·96'N 104°03·03'E

502	9 Ed 15/10/21 Last NM 53/2024 (Maritime and Port Authority of Singapore)	*NM 66/2024
Insert	the accompanying block, centred on:	1°20·16'N 104°02·84'E

*Source: Maritime and Port Authority of Singapore

II TEMPORARY AND PRELIMINARY NOTICES

***(NM 67T/2024) : OBSTRUCTIONS EXIST OFF ADVARIO SINGAPORE JETTY**

Description : 1. Three obstructions with least depth below CD exist off Advorio Singapore Jetty.

Depth	Position
3·3m	1°17·475'N, 103°43·333'E
13·4m	1°17·417'N, 103°43·477'E
15·6m	1°17·253'N, 103°43·697'E

2. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, Dual Badged BA4034

ENCs affected : SG5C4034

***(NM 68P/2024) : LEAST DEPTHS CHANGED AT ADVARIO SINGAPORE JETTY**

Description : 1. Least depths alongside have changed for the following berths:

Berth	Depth Alongside (Year Surveyed)	Position
OTK 1	14·1m (2024)	1°16·703'N, 103°44·270'E
OTK 2	13·7m (2024)	1°16·765'N, 103°44·272'E
OTK 3	14·0m (2024)	1°16·756'N, 103°44·213'E
OTK 4	13·7m (2024)	1°16·882'N, 103°44·145'E
OTK 5	13·1m (2024)	1°16·813'N, 103°44·148'E
OTK 9	15·9m (2024)	1°16·632'N, 103°44·408'E
OTK 18	15·7m (2024)	1°17·520'N, 103°43·437'E


2. Mariners are advised to navigate with caution.

Charts affected : Dual Badged BA4034

ENCs affected : SG5C4034


*Source: Maritime and Port Authority of Singapore

To accompany Notice to Mariners. Image Size (mm) 87.3 x 56.7




Block for Chart No GSP1

To accompany Notice to Mariners. Image Size (mm) 87.3 x 56.7



Block for Chart No GSP1

To accompany Notice to Mariners. Image Size (mm) 132 x 60



Block for Chart No 502