



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Notices to Mariners and Chart Corrections	1
III	Amendments to Publications	2

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Department, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
<http://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm>

Hydrographic Department
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : (65) 6325 2027
Fax : (65) 6226 1076
Email : hydrographic@mpa.gov.sg
Website : www.mpa.gov.sg

II

NOTICES TO MARINERS AND CHART CORRECTIONS

GSP1/SP1		3 Ed 15/1/18 Last NM 51/2018	(Maritime and Port Authority of Singapore)	NM 58/2018	
Insert	 FI(2)R.5s			1°15·16'N	103°39·13'E
Insert	 FI(2)R.7s			1°14·63'N	103°39·34'E
Move	 FI.R.4s from:			1°15·44'N	103°38·71'E
	to:			1°15·44'N	103°38·87'E
Delete	 FI(3)R.15s			1°14·55'N	103°39·13'E
Insert	 FI(3)R.15s			1°14·10'N	103°39·41'E

III AMENDMENTS TO PUBLICATIONS

*(NM 59/2018) UPDATING OF PUBLICATION “SINGAPORE PORT INFORMATION 2018/2019”

CHARACTERISTICS OF AIDS TO NAVIGATION

1. Page 132

TUAS VIEW EXTENSION

Amend the following:

Name Of Beacon/Buoy	Position Lat. N Long. E	Structure, Colour & Shape	Light Characteristic	Owner
F2-DDJV-3 Buoy	01°15·440' 103°38·871'	Red pillar with can topmark	Fl.R.4s	DIAP-DAELIM Joint Venture
F2-DDJV-4 Buoy	01°14·096' 103°39·413'	Red pillar with can topmark	Fl(3)R.15s	DIAP-DAELIM Joint Venture

Insert the following:

Name Of Beacon/Buoy	Position Lat. N Long. E	Structure, Colour & Shape	Light Characteristic	Owner
F2-DDJV-3A Buoy	01°15·160' 103°39·131'	Red pillar with can topmark	Fl(2)R.5s	DIAP-DAELIM Joint Venture
F2-DDJV-3B Buoy	01°14·633' 103°39·342'	Red can with can topmark	Fl(2)R.7s	DIAP-DAELIM Joint Venture

Delete the following:

Name Of Beacon/Buoy	Position Lat. N Long. E	Structure, Colour & Shape	Light Characteristic	Owner
DDJV-MB-3 Mooring Buoy	01°14·456' 103°38·145'	Yellow can	Fl(5)Y.20s	DIAP-DAELIM Joint Venture
DDJV-MB-4 Mooring Buoy	01°14·457' 103°38·517'	Yellow can	Fl(5)Y.20s	DIAP-DAELIM Joint Venture

*Source: Maritime and Port Authority of Singapore