

## SINGAPOREAN NOTICES TO MARINERS

## SECTION CONTENT

Page

1

II

Temporary and Preliminary Notices

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website: <u>http://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm</u>

Hydrographic Division Maritime and Port Authority of Singapore 7B Keppel Road #20-00 Tanjong Pagar Complex Singapore 089055 Tel : (65) 6325 2027 Fax : (65) 6226 1076 Email : <u>hydrographic@mpa.gov.sg</u> Website : www.mpa.gov.sg

## **TEMPORARY AND PRELIMINARY NOTICES**

*(NM 72T/2019)		MAIN	MAINTENANCE OF OUTER SHOAL BEACON	
Description	:	1.	Outer Shoal Beacon at position 1°15·015'N 103°51·808'E has been removed for maintenance.	
		2.	A temporary green conical buoy with light characteristics FI.G.5s has been installed at position 1°15·016'N 103°51·777'E.	
		3.	Mariners are advised to navigate with caution.	
Charts affected	:	Singaporean GSP1/SP1, 501, 502, Dual Badged BA4037, BA4040, and BA4041		
<i>Note :</i> Former Notice 49T/2019 has been cancelled.				
Source : Maritime and Port Authority of Singapore				