



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Department, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
<http://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm>

Hydrographic Department
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : (65) 6325 2027
Fax : (65) 6226 1076
Email : hydrographic@mpa.gov.sg
Website : www.mpa.gov.sg

II

TEMPORARY AND PRELIMINARY NOTICES

(NM 39T/2019)

REPAIR OF OUTER SHOAL BEACON

- Description** : 1. Outer Shoal Beacon has been temporarily removed for repair and replaced by a green conical buoy with light characteristic Fl.G.5s at position 01°15·016'N 103°51·777'E.
2. Outer Shoal Beacon will be reinstalled at the original position upon completion of repair.
- Chart affected** : Singaporean GSP1/SP1, 501, 502, Dual Badged BA4037, BA4040 and BA4041
- Caution** : Mariners are advised to navigate with caution

Source : Maritime and Port Authority of Singapore
