



## SINGAPOREAN NOTICES TO MARINERS

---

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1
III	Navigational Information	2

---

**This supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Department, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected. Notices under Section II apply only to the particular Singaporean Chart(s) indicated.**

---

This supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:  
[http://www.mpa.gov.sg/sites/port\\_and\\_shipping/circulars\\_and\\_notices/singapore\\_notices\\_to\\_mariners\(ntm\).page](http://www.mpa.gov.sg/sites/port_and_shipping/circulars_and_notices/singapore_notices_to_mariners(ntm).page)

Hydrographic Department  
Maritime and Port Authority of Singapore  
7B Keppel Road  
#20-00 Tanjong Pagar Complex  
Singapore 089055  
Tel: (65) 6325 2027  
Fax: (65) 6226 1076  
Email: [hydrographic@mpa.gov.sg](mailto:hydrographic@mpa.gov.sg)

## II TEMPORARY AND PRELIMINARY NOTICES

### \*(NM 81P/2015) TEMPORARY RE-ALIGNMENT OF TEMASEK FAIRWAY AND WEST JURONG CHANNEL


1. The Maritime and Port Authority of Singapore (MPA) would like to inform mariners that the boundaries of Temasek Fairway and West Jurong Channel will be re-aligned. The re-alignment includes changes to the boundaries of the existing Temasek Fairway and West Jurong Channel and re-location of navigational buoys. **The re-alignment will come into effect at 0001H on 1 October 2015.**
2. The revised boundaries of Temasek Fairway and West Jurong Channel are bounded by a line joining the following geographical positions:

		(WGS 84 Datum)		
		Latitude (N)	Longitude (E)	
Temasek Fairway line joining to:	(3)	1° 16-297'	103° 38-709'	F1JV-03 Buoy
	(4)	1° 16-582'	103° 38-709'	
Temasek Fairway line joining to:	(11)	1° 15-630'	103° 39-216'	Triton Buoy
	(10)	1° 16-485'	103° 39-216'	
West Jurong Channel line joining   to:	(4)	1° 16-582'	103° 38-709'	SCM 5 Buoy Long Shoal Buoy
	(5)	1° 16-727'	103° 39-015'	
	(6)	1° 17-084'	103° 39-765'	
	(7)	1° 17-400'	103° 40-432'	
West Jurong Channel line joining   to:	(10)	1° 16-485'	103° 39-216'	Triton Buoy
	(9)	1° 16-585'	103° 39-342'	
		1° 16-671'	103° 39-529'	DIAP-WJ1 Buoy
	(8)	1° 17-170'	103° 40-579'	

3. These changes are shown in the accompanying diagram, however there may be amendments as the work progresses. Mariners are advised to consult local authorities and refer to updated information available in relevant MPA Port Marine Notices at <http://www.mpa.gov.sg>.
4. Charts affected : Singaporean Charts GSP1, SP1 and 501.  
Dual Badged Charts 4030, 4031, 4033, 4038 and 4040.

---

\*Source: Maritime and Port Authority of Singapore



### III NAVIGATIONAL INFORMATION

**\*(NM 82/2015) SINGAPORE PORT MARINE NOTICES**

The Port Marine Notices shortlisted below would be of particular interest to mariners. Details and complete list of Port Marine Notices are available at this link:

[http://www.mpa.gov.sg/sites/port\\_and\\_shipping/circulars\\_and\\_notices/port\\_marine\\_notices.page](http://www.mpa.gov.sg/sites/port_and_shipping/circulars_and_notices/port_marine_notices.page)

<b>PMN No.</b>	<b>Subject</b>
106/2015	Conduct of Harbour Craft during reduced visibility in the Port of Singapore.

---

\*Source: Maritime and Port Authority of Singapore