



## SINGAPOREAN NOTICES TO MARINERS

| SECTION | CONTENT                           | Page |
|---------|-----------------------------------|------|
| II      | Temporary and Preliminary Notices | 1    |

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:  
[www.mpa.gov.sg/media-centre](http://www.mpa.gov.sg/media-centre)

**MPA Telegram Channel:** MPA has launched a Telegram channel for notices and circulars. To stay updated, please subscribe via the following link <https://go.gov.sg/mpa-telegram> or scan the QR code:



<https://go.gov.sg/mpa-telegram>

**Contact information:**

Hydrographic Division  
Maritime and Port Authority of Singapore  
7B Keppel Road  
#20-00 Tanjong Pagar Complex  
Singapore 089055  
Tel : 1800 272 7777 / (65) 6272 7777  
Email : [hydrographic@mpa.gov.sg](mailto:hydrographic@mpa.gov.sg)

**II**  
**TEMPORARY AND PRELIMINARY NOTICES**

**\*(NM 25P/2023) : OBSTRUCTION EXISTS OFF PULAU TEKONG**

Description : 1. An obstruction, depth 5·5m below CD, at position Lat 1°24·24'N Long 104°05·34'E, exists off Pulau Tekong.  
2. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, 202, 502, Dual Badged BA4043

ENC affected : SG5C4043

---

**\*(NM 26P/2023) : ROCK EXISTS OFF PULAU TEKONG**

Description : 1. A rock, depth 8·7m below CD, at position Lat 1°23·02'N Long 104°00·72'E, exists off Pulau Tekong.  
2. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, 202, 502, Dual Badged BA4043 & BA4044

ENC affected : SG5C4043

---

\*Source: Maritime and Port Authority of Singapore