



## SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:

[www.mpa.gov.sg/media-centre](http://www.mpa.gov.sg/media-centre)

**MPA Telegram Channel:** MPA has launched a Telegram channel for notices and circulars. To stay updated, please subscribe via the following link <https://go.gov.sg/mpa-telegram> or scan the QR code:



<https://go.gov.sg/mpa-telegram>

**Contact information:**

Hydrographic Division

Maritime and Port Authority of Singapore

7B Keppel Road

#20-00 Tanjong Pagar Complex

Singapore 089055

Tel : 1800 272 7777 / (65) 6272 7777

Email : [hydrographic@mpa.gov.sg](mailto:hydrographic@mpa.gov.sg)

**II**  
**TEMPORARY AND PRELIMINARY NOTICES**

**\*(NM 32P/2023) : MISSING BUOY OFF TUAS VIEW EXTENSION**

Description : 1. The *HVB-8A* starboard-hand conical light-buoy, Fl.G.4s, at position Lat 01°15·860'N, Long 103°36·290'E, is reported missing.  
2. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, 500, 501, Dual Badged BA4038, BA4038 Inset C & BA4040

ENC affected : SG5C4038

---

\*Source: Maritime and Port Authority of Singapore