

BRIDGE TEAMS ONBOARD *ANL INDONESIA* AND *RSS COURAGEOUS* AT THE TIME OF THE COLLISION

Bridge Team of *ANL Indonesia*:

Rank & Appointment	Function on the Bridge
Master	Supervising Officer on the Bridge, responsible for safe navigation
Marine-Officer 4	Officer on the Watch – in charge of navigation
AB	Lookout and steersman
Cadet	Trainee (he was at the chart table and did not witness the collision)
Marine Officer 2	Duty officer for monitoring machinery spaces (he did not witness the collision)

Bridge Team of *RSS Courageous*:

At the time of the incident, the naval vessel was under the command of Major Tang Yang Yong. Please approach RSN for the particulars of the RC bridge crew.

	Rank & Appointment	Function on the Bridge
1	LTA -Executive Officer (XO)	The Officer of the Watch (OOW), responsible for safe navigation
2	LTA - Additional Officer (AO)	Trainee Officer who was performing duty as trainee OOW (assistant OOW)
3	1 st Sergeant (1SG)	Petty Officer of the Watch (POOW)
4	2 SG	Radar Plotter
5	2 SG	Helmsman Supervisor
6	3 SG	Trainee Helmsman
7	1 SG	Lookout
8	Corporal (CPL)	Trainee Lookout