



## SINGAPOREAN NOTICES TO MARINERS

---

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1
III	Amendments to Publications	2

---

**The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port authority of Singapore. The information contained in these Notices should be updated on the charts affected.**

---

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:  
<https://www.mpa.gov.sg/web/portal/home/port-of-singapore/circulars-and-notices/singapore-notices-to-mariners-ntm>

Hydrographic Division  
Maritime and Port Authority of Singapore  
7B Keppel Road  
#20-00 Tanjong Pagar Complex  
Singapore 089055  
Tel : (65) 6325 2027  
Fax : (65) 6226 1076  
Email : [hydrographic@mpa.gov.sg](mailto:hydrographic@mpa.gov.sg)  
Website : [www.mpa.gov.sg](http://www.mpa.gov.sg)

## II

**TEMPORARY AND PRELIMINARY NOTICES****Cancelled Temporary and Preliminary Notices**

<i>No. of Notice</i>	<i>Subject</i>	<i>Charts affected</i>
31T/2020	Maintenance of Outer Shoal Beacon	Singaporean GSP1/SP1, 501 and 502 Dual-Badged BA4037, BA4040 and BA4041

### III AMENDMENTS TO PUBLICATIONS

\*(NM 71/2020) UPDATING OF PUBLICATION “SINGAPORE PORT INFORMATION 2020/2021”

#### CHARACTERISTICS OF AIDS TO NAVIGATION

1. Page 145  
**EAST KEPPEL FAIRWAY**  
Amend the following:

Name of Beacon/ Buoy	Position Lat. N Long. E Deg Min	Structure, Colour & Shape	Light Characteristic	Owner
Outer Shoal Beacon	<b>1°15·014’ 103°51·808’</b>	Green triangle on green tubular tower pivoted at base, Buoyant beacon	Fl.G.5s.8m5M	MPA