



SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:
www.mpa.gov.sg/media-centre

MPA Telegram Channel: MPA has launched a Telegram channel for notices and circulars. To stay updated, please subscribe via the following link <https://go.gov.sg/mpa-telegram> or scan the QR code:



<https://go.gov.sg/mpa-telegram>

Contact information:

Hydrographic Division
Maritime and Port Authority of Singapore
7B Keppel Road
#20-00 Tanjong Pagar Complex
Singapore 089055
Tel : 1800 272 7777 / (65) 6272 7777
Email : hydrographic@mpa.gov.sg

II

TEMPORARY AND PRELIMINARY NOTICES

***(NM 8T/2023) : LEAST DEPTHS WITHIN THE TURNING CIRCLE AT CRUISE BAY**

Description : 1. Two least depths, 9.3m below CD at position Lat 1°15'736"N Long 103°49'376'E and 8.3m below CD at position Lat 1°15'667"N Long 103°49'375'E exists within the Turning Circle at Cruise Bay.

2. Mariners are advised to navigate with caution.

Charts affected : Dual Badged BA4035

ENCs affected : SG5C4035

***(NM 9T/2023) : SUNKEN VESSEL IN SUDONG SPECIAL PURPOSE (ASSPU) ANCHORAGE**

Description : 1. A sunken vessel 'SMF 927' has been reported at position Latitude 1°10'747"N Longitude 103°42'515'E with least depth 25.9m below CD within Sudong Special Purpose (ASSPU) Anchorage.

2. The sunken vessel may drift from the reported position.

3. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, 500, 501, Dual Badged BA4031,BA4039, BA4040

ENCs affected : SG5C4031

*Source: Maritime and Port Authority of Singapore.