



## SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1
	Cancelled Temporary and Preliminary Notices	2

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:  
[www.mpa.gov.sg/media-centre](http://www.mpa.gov.sg/media-centre)

**MPA Telegram Channel:** MPA has launched a Telegram channel for notices and circulars. To stay updated, please subscribe via the following link <https://go.gov.sg/mpa-telegram> or scan the QR code:



<https://go.gov.sg/mpa-telegram>

### Contact information:

Hydrographic Division  
Maritime and Port Authority of Singapore  
7B Keppel Road  
#20-00 Tanjong Pagar Complex  
Singapore 089055  
Tel : 1800 272 7777 / (65) 6272 7777  
Email : [hydrographic@mpa.gov.sg](mailto:hydrographic@mpa.gov.sg)

## II

## TEMPORARY AND PRELIMINARY NOTICES

**\*(NM 56T/2024) : SUNKEN VESSEL 'JOLLY RANGER' AT EASTERN SPECIAL PURPOSES A ANCHORAGE (AESPA)**

- Description : 1. A sunken vessel 'Jolly Ranger' has been reported at position Lat 1°17'38'N Long 103°58'01'E with least depth 29.6m below CD within Eastern Special Purposes A Anchorage (AESPA).
2. A virtual isolated danger buoy with MMSI no. 995636003 has been established at the same position to mark the sunken vessel.
3. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, 202, 502, Dual Badged BA4041,BA4043

ENCs affected : SG5C4041

**\*(NM 57P/2024) : LEAST DEPTHS CHANGED AT TANJONG PAGAR TERMINAL BERTHS T6 AND T7**

- Description : 1. Least depths alongside have changed for the following berths:

Berth	Depth Alongside (Year Surveyed)
T6	11.9m (2024)
T7	9.7m (2024)

2. Mariners are advised to navigate with caution.
3. Former Notice 68T/23 is cancelled.

Charts affected : Dual Badged BA4037

ENCs affected : SG5C4037

\*Source: Maritime and Port Authority of Singapore.

**II**  
**TEMPORARY AND PRELIMINARY NOTICES**

**Cancelled Temporary and Preliminary Notices**

<i>No. of Notices</i>	<i>Subject</i>	<i>Charts Affected</i>
68T/2023	Least depths exist within Tanjong Pagar Terminal Berths T6 & T7	Dual Badged BA4037 Singaporean ENC SG5C4037