



## SINGAPOREAN NOTICES TO MARINERS

SECTION	CONTENT	Page
II	Temporary and Preliminary Notices	1
IV	Reprint of Maritime Safety Information	2

The supplementary Singaporean Notices to Mariners contains corrective information affecting charts published by the Hydrographic Division, Maritime and Port Authority of Singapore. The information contained in these Notices should be updated on the charts affected.

The supplementary Singaporean Notices to Mariners can be accessed directly from the MPA website:  
[www.mpa.gov.sg/media-centre](http://www.mpa.gov.sg/media-centre)

**MPA Telegram Channel:** MPA has launched a Telegram channel for notices and circulars. To stay updated, please subscribe via the following link <https://go.gov.sg/mpa-telegram> or scan the QR code:



<https://go.gov.sg/mpa-telegram>

**Contact information:**

Hydrographic Division  
Maritime and Port Authority of Singapore  
7B Keppel Road  
#20-00 Tanjong Pagar Complex  
Singapore 089055  
Tel : 1800 272 7777 / (65) 6272 7777

**II**  
**TEMPORARY AND PRELIMINARY NOTICES**

**\*(NM 39T/2025) : SUNKEN VESSEL 'KSE HITACHI GO' OFF TUAS WESTERN COAST**

Description : 1. The sunken vessel 'KSE HITACHI GO' is located at position Lat 1°18'117"N Long 103°37'004'E.

2. A virtual AtoN (isolated danger mark) with MMSI no. 995636004 has been established at position Lat 1°18'125"N Long 103°36'945'E to mark the sunken vessel.

3. An isolated danger buoy, with light characteristics Fl(2)10s, has also been established at the same position.

4. Mariners are advised to navigate with caution.

Charts affected : Singaporean GSP1/SP1, Dual Badged BA4038, BA4040

ENCs affected : SG5C4038

---

\*Source: Maritime and Port Authority of Singapore

**IV**

**REPRINT OF MARITIME SAFETY INFORMATION**

TT201

AN ISOLATED DANGER BUOY FL(2)W.10S AT POSITION LAT 01-18.125'N LONG 103-36.945'E TO MARK A PARTIALLY SUBMERGED DREDGER KSE HITACHI GO HAS BEEN DEPLOYED. A VIRTUAL ATON WITH MMSI NO 995636004 OF THE SAME CHARACTERISTIC HAS ALSO BEEN DEPLOYED IN THE SAME POSITION. ALL VESSELS NAVIGATING IN THE VICINITY ARE ADVISED TO NAVIGATE WITH CAUTION.

---

ISSUED BY SINGAPORE PORT OPERATIONS CONTROL CENTRE (as at 15<sup>th</sup> April 2025)