



## SINGAPOREAN NOTICES TO MARINERS

---

SECTION	CONTENT	Page
II	Notices to Mariners and Chart Corrections	1
III	Amendments to Publications	2

---

The monthly Notices to Mariners contain information required to keep charts and publications published by the Hydrographic Division, Maritime and Port Authority of Singapore up-to-date.

Mariners are requested to notify the Chief Hydrographer, Maritime and Port Authority of Singapore, immediately of the discovery of new or suspected dangers to navigation, observed changes to aids to navigation and ways Singaporean Charts and Publications can be improved. The Hydrographic Note on the back page should be used for this purpose.

Detailed information of charts and publications (coverage of charts, latest editions and distributors) are available on the Maritime and Port Authority of Singapore's Website: [www.mpa.gov.sg](http://www.mpa.gov.sg)

- [Singaporean Notice to Mariners](#)
- [Singaporean Charts](#)
- [Dual-Badged Charts](#)
- [Singapore ENC](#)
- [Malacca and Singapore Straits ENC](#)
- [Singapore Port Information](#)
- [Singapore Tide Tables](#)

**Contact information:**

Hydrographic Division  
Maritime and Port Authority of Singapore  
7B Keppel Road  
#20-00 Tanjong Pagar Complex  
Singapore 089055  
Tel : 1800 272 7777 / (65) 6272 7777  
Email : [hydrographic@mpa.gov.sg](mailto:hydrographic@mpa.gov.sg)

**II**  
**NOTICES TO MARINERS AND CHART CORRECTIONS**

**GSP1/SP1** 10 Ed 14/01/26 Last NM 17/2026 (Maritime and Port Authority of Singapore) **\*NM 21/2026**

**Replace**  *Fl. Y. 5s, Shell SBM* with  *Fl. Y. 5s, Aster SBM* 1°11·47'N 103°47·43'E

---

**CORRIGENDUM TO SNM03/18/2026**

**500** 8 Ed 15/09/17 Last NM 105/2025 (Maritime and Port Authority of Singapore) **\*NM 22/2026**

**Move**  *Fl. G. 2s, PKHDB-21* from: 1°14·37'N 103°36·27'E  
to: 1°14·42'N 103°36·27'E

---

**501** 7 Ed 01/09/15 Last NM 18/2026 (Maritime and Port Authority of Singapore) **\*NM 21/2026**

**Replace**  *Fl. Y. 5s, Shell SBM* with  *Fl. Y. 5s, Aster SBM* 1°11·47'N 103°47·43'E

**CORRIGENDUM TO SNM03/18/2026**

(Maritime and Port Authority of Singapore) **\*NM 22/2026**

**Move**  *Fl. G. 2s, PKHDB-21* from: 1°14·37'N 103°36·27'E  
to: 1°14·42'N 103°36·27'E

---

\*Source: Maritime and Port Authority of Singapore

**III**  
**AMENDMENTS TO PUBLICATIONS**

**\*(NM 23/2026) UPDATING OF PUBLICATION “SINGAPORE PORT INFORMATION 2025”**

The Singapore Port Information 2025 including the following updates can be accessed directly from MPA Website:

<https://www.mpa.gov.sg/who-we-are/newsroom-resources/publications/singapore-port-information>

**CHARACTERISTIC OF AIDS TO NAVIGATION**

**1. Page 63**

**APPROACHES TO ASTER SBM**

**Amend** the following:

<b>Name Of Beacon / Buoy</b>	<b>Position Lat. N Long.</b>	<b>Structure, Colour &amp; Shape</b>	<b>Light Characteristic</b>	<b>Owner</b>
<b>Aster SBM Buoy</b>	01°11.468' 103°47.429'	Yellow can	Fl.Y.5s	Aster Chemicals & Energy Pte Ltd

---

\*Source: Maritime and Port Authority of Singapore

103°45'E

1°10'N



CORRECTION NO.	SNM EDN NO.	LAST CORR NO.	CHART NO.	Location on Chart		
21	3A	17	GSP1/SP1		X	

Caution : some computer printers might distort the tracings.  
Users are advised to check and, if necessary, adjust settings on the printer



103°35'E


1°10'N

CORRECTION NO.	SNM EDN NO.	LAST CORR NO.	CHART NO.	Location on Chart		
22	3A	105/2025	500			X

Caution : some computer printers might distort the tracings.  
Users are advised to check and, if necessary, adjust settings on the printer


103°45'E

1°10'N



CORRECTION NO.	SNM EDN NO.	LAST CORR NO.	CHART NO.	Location on Chart		
						X
21	3A	18	501			

Caution : some computer printers might distort the tracings.  
Users are advised to check and, if necessary, adjust settings on the printer



CORRECTION NO.	SNM EDN NO.	LAST CORR N NO.	CHART NO.	Location on Chart		
				X		
22	3A	21	501			

Caution : some computer printers might distort the tracings.  
 Users are advised to check and, if necessary, adjust settings on the printer